

## Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		1 William St	1 William St-/8-1045	NO	UNK		C	UNK	
1.0.3	1059000		7 William St	7 William St-/8-1050	NO	UNK		C	UNK	
1.0.3	1059000		9 William St	9 William St-/8-1056	NO	UNK		C	UNK	
1.0.3	1059000		13 William St	13 William St-/8-1065	NO	UNK		C	UNK	
1.0.3	1059000		11 William St	11 William St-/8-1060	NO	UNK		C	UNK	
1.0.3	1059000		17 William St	17 William St-/8-1070	NO	UNK		C	UNK	
1.0.3	1059000		114 Route 20	114 Route 20-/8-1005	NO	UNK		C	UNK	1"
1.0.3	1059000		110 Route 20	110 Route 20-/8-1000	NO	UNK		C	UNK	1"
1.0.3	1059000		19 William St	19 William St-/8-1075	NO	UNK		C	UNK	
1.0.3	1059000		166 Route 20	166 Route 20-/8-1035	NO	UNK		C	UNK	1"
1.0.3	1059000		158 Route 20	158 Route 20-/8-1020	NO	UNK		C	UNK	1"
1.0.3	1059000		116 Route 20	116 Route 20-/8-1010	NO	UNK		C	UNK	1"
1.0.3	1059000		162 Route 20	162 Route 20-/8-1025	NO	UNK		C	UNK	1"
1.0.3	1059000		172 Route 20	172 Route 20-/8-1040	NO	UNK		C	UNK	1"
1.0.3	1059000		146 Route 20	146 Route 20-/8-1015	NO	UNK		C	UNK	1"
1.0.3	1059000		21 William St	21 William St-/8-1080	YES	UNK		C	UNK	
1.0.3	1059000		23 William St	23 William St-/8-1086	YES	UNK		C	UNK	
1.0.3	1059000		164 Route 20	164 Route 20-/8-1031	NO	UNK		C	UNK	1"
1.0.3	1059000		25 William St	25 William St-/8-1091	NO	UNK		C	UNK	
1.0.3	1059000		18 William St	18 William St-/8-1136	NO	UNK		C	UNK	
1.0.3	1059000		14 William St	14 William St-/8-1140	NO	UNK		C	UNK	
1.0.3	1059000		29 William St	29 William St-/8-1100	NO	UNK		C	UNK	
1.0.3	1059000		31 William St	31 William St-/8-1105	NO	UNK		C	UNK	
1.0.3	1059000		27 William St	27 William St-/8-1095	NO	UNK		C	UNK	
1.0.3	1059000		26 William St	26 William St-/8-1115	NO	UNK		C	UNK	
1.0.3	1059000		8 William St	8 William St-/8-1150	NO	UNK		C	UNK	
1.0.3	1059000		30 William St	30 William St-/8-1111	NO	UNK		C	UNK	
1.0.3	1059000		24 William St	24 William St-/8-1120	NO	UNK		C	UNK	
1.0.3	1059000		4 William St	4 William St-/8-1155	NO	UNK		C	UNK	
1.0.3	1059000		10 William St	10 William St-/8-1145	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		22 William St	22 William St-/8-1125	NO	UNK		C	UNK	
1.0.3	1059000		20 William St	20 William St-/8-1130	NO	UNK		C	UNK	

Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	C	3/4"	2021	NON-LEAD	F	V	SF
1993	HDPE	1"	PLB	NON-LEAD	F	V	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2010	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	C	V	SF
2010	C	3/4"	PLB	NON-LEAD	F	V	SF
2010	C	1"	PLB	NON-LEAD	F	V	SF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2010	C	3/4"	PLB	NON-LEAD	F	V	SF
2010	C	1/2"	PLB	NON-LEAD	F	V	SF
2010	C	3/4"	ALB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	C	3/4"	ALB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	SF

Chester-1059000-Service\_Line\_In

poe_pou_treatment	building_plumbing_material_1	building_plumbing_material_2	building_plumbing_material_install_date	sampling_plan_location	tier	replaced_sl	replaced_material
NO	C						
YES	C						
	C						
NO	C						
YES	C						
UNK	UNK		1900	R	TIER 4		
UNK	UNK		1875	R	TIER 4		
NO	C						
NO							
NO	C						
YES	C						

replacement_date	comments
	Basement Inspection conducted by PWS
	Basement inspection conducted 12/22/23
	Statistical Analysis on Private Side
	Basement Inspection conducted on 8/3/24
	Basement inspection conducted 1/8/2024
	Statistical Analysis on Private Side
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010. Statistical Analysis on Private Side
	Basement inspection conducted 1/23/2024 and noted copper interior plumbing; Record drawing confirmed public side was replaced in 2010 when the main
	Self-reported photos confirm private side material is copper
	Basement inspection conducted 12/8/2023; Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010.
	Basement inspection conducted 5/1/2024; Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010.
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010. Statistical Analysis on Private Side
	Basement Inspection Conducted 8/30/24; Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010.
	Basement inspection conducted 1/8/2024; water service tapped off of main on
	Basement inspection conducted 4/5/2024 and noted point of entry treatment system is present; Record drawing confirmed public side was replaced in 2010
	Basement inspection conducted 1/8/2024
	Basement inspection conducted 1/8/2024; Second basement inspection
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010. Statistical Analysis on Private Side
	Basement inspection conducted 1/8/2024
	Statistical Analysis on Private Side
	Basement inspection conducted 1/8/2024
	Statistical Analysis on Private Side
	Basement inspection conducted 8/3/24
	Basement inspection conducted 1/8/2024
	Basement inspection conducted 9/16/2024
	Basement inspection conducted 8/3/24
	Statistical Analysis on Private Side
	PWS private side inspection 7-7-25
	Basement inspection conducted 1/8/2024
	Statistical Analysis on Private Side
	Basement Inspection conducted 8/3/24
	Basement inspection conducted 12/22/2023

## Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		185 Route 20	185 Route 20-/8-1165	NO	UNK		C	UNK	1"
1.0.3	1059000		191 Route 20	191 Route 20-/8-1190	NO	UNK		C	UNK	1"
1.0.3	1059000		187 Route 20	187 Route 20-/8-1180	NO	UNK		C	UNK	1"
1.0.3	1059000		175 Route 20	175 Route 20-/8-1177	NO	UNK		C	UNK	1"
1.0.3	1059000		165 Route 20	165 Route 20-/8-1175	NO	UNK		C	UNK	1"
1.0.3	1059000		180 Route 20	180 Route 20-/8-1160	NO	UNK		C	UNK	1"
1.0.3	1059000		3 School St	3 School St-/8-1200	NO	UNK		C	UNK	
1.0.3	1059000		11 School St	11 School St-/8-1217	NO	UNK		C	UNK	
1.0.3	1059000		13 School St	13 School St-/8-1222	NO	UNK		C	UNK	
1.0.3	1059000		9 School St	9 School St-/8-1210	NO	UNK		C	UNK	
1.0.3	1059000		17 School St	17 School St-/8-1220	NO	UNK		C	UNK	
1.0.3	1059000		2 School St	2 School St-/8-1226	NO	UNK		C	UNK	
1.0.3	1059000		17 Olin Ave	17 Olin Ave-/8-1255	YES	UNK		C	UNK	3/4"
1.0.3	1059000		11 Olin Ave	11 Olin Ave-/8-1265	NO	UNK		C	UNK	3/4"
1.0.3	1059000		14 Olin Ave	14 Olin Ave-/8-1260	NO	UNK		C	UNK	3/4"
1.0.3	1059000		10 Olin Ave	10 Olin Ave-/8-1270	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		166 Middlefield Rd	166 Middlefield Rd-/8-1235	NO	UNK		C	UNK	
1.0.3	1059000		126 Middlefield Rd	126 Middlefield Rd-/8-	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		10 Middlefield Rd	10 Middlefield Rd-/8-1230	NO	UNK		C	UNK	1"
1.0.3	1059000		156 Middlefield Rd	156 Middlefield Rd-/8-	NO	UNK		C	UNK	
1.0.3	1059000		130 Middlefield Rd	130 Middlefield Rd-/8-	NO	UNK		C	UNK	
1.0.3	1059000		106 Middlefield Rd	106 Middlefield Rd-/8-1290	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		110 Middlefield Rd	110 Middlefield Rd-/8-	NO	UNK		C	UNK	1"
1.0.3	1059000		114 Middlefield Rd	114 Middlefield Rd-/8-	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		96 Middlefield Rd	96 Middlefield Rd-/8-1302	NO	UNK		C	UNK	1"
1.0.3	1059000		94 Middlefield Rd	94 Middlefield Rd-/8-1305	NO	UNK		C	UNK	1"
1.0.3	1059000		90 Middlefield Rd	90 Middlefield Rd-/8-1311	NO	UNK		C	UNK	1"
1.0.3	1059000		101 Middlefield Rd	101 Middlefield Rd-/8-1325	NO	UNK		C	UNK	1"

## Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
2010	C	1"	PLB	NON-LEAD	F	V	SF
2010	UNK-NOLG	2"	PLB	NON-LEAD	F	V	MIX
2010	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2010	C	3/4"	PLB	NON-LEAD	F	V	MF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	MF
2010	C	3/4"	PLB	NON-LEAD	F	V	MF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
PLB	HDPE	1"	1945	NON-LEAD	F	V	SF
PLB	UNK-NOLG		PLB	NON-LEAD	F	A	MF
PLB	C	3/4"	PLB	NON-LEAD	F		SF
PLB	C	3/4"	PLB	NON-LEAD	F	A	SF
PLB	UNK-NOLG	3/4"	PLB	NON-LEAD	V	A	SF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
2003	C	2"	PLB	NON-LEAD	F	V	MF
PLB	C	3/4"	1984	NON-LEAD	F	V	SF
2022	C		2022	NON-LEAD	F		SF
PLB	C	3/4"	PLB	NON-LEAD	F	A	SF
PLB	B	3/4"	PLB	NON-LEAD	F	V	SF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2003	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	C	3/4"	PLB	NON-LEAD	V		SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF



replacement_date	comments
	Basement inspection conducted 5/1/2024; Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010.
	Chester Village Market. Basement inspection conducted 1/8/2024 indicated cast iron, but unknown if lined or unlined; Record drawing confirmed public side
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010. Statistical Analysis on Private Side
	Basement Inspection conducted 8/10/24; Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010.
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010. Statistical Analysis on Private Side
	Basement Inspection conducted 8/30/24; Record drawing confirmed public side was replaced in 2010 when the main was replaced in August 2010.
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Unable to determine private side material from self-reported photos - additional photos/tests required Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Self-reported photos show sleeved private side service line or HDPE. Vacuum
	Vacuum Excavation conducted 2024 Statistical Analysis on Private Side
	7-21-25 PWS Inspection. Vacuum Excavation conducted 2024
	Basement inspection conducted on 8/3/24. Statistical Analysis on Public Side
	Unable to determine private side material from self reported photos - additional tests/photos required Statistical Analysis on Private Side
	Statistical Analysis on Public Side Statistical Analysis on Private Side
	Former Chester Elementary School; Basement inspection conducted 11/18/2024; Record drawing confirmed public side replaced in 2003 when the
	Basement Inspection Conducted on 7/27/24
	Line was replaced by water department in 2022
	Basement inspection conducted 3/22/2024; Self-reported photos confirm private side material is copper Statistical Analysis on Public Side
	Basement inspection done on 8/18/25 showed service was brass.
	Statistical Analysis on Public Side Statistical Analysis on Private Side
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003 Statistical Analysis on Private Side
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Private inspection done by town on 8/25/25
	Record drawing confirmed public side replaced in 2003 when the main was
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Basement inspection completed o 8/3/2024

## Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		85 Middlefield Rd	85 Middlefield Rd-/8-1320	NO	UNK		C	UNK	1"
1.0.3	1059000		86 Middlefield Rd	86 Middlefield Rd-/8-1315	NO	UNK		C	UNK	1"
1.0.3	1059000		5-7 School St	5-7 School St-/8-1205	NO	UNK		C	UNK	
1.0.3	1059000		20 Morey Ave	20 Morey Ave-/8-1330	NO	UNK		C	UNK	
1.0.3	1059000		76 Middlefield Rd	76 Middlefield Rd-/8-1350	NO	UNK		C	UNK	1"
1.0.3	1059000		78 Middlefield Rd	78 Middlefield Rd-/8-1345	NO	UNK		C	UNK	1"
1.0.3	1059000		80 Middlefield Rd	80 Middlefield Rd-/8-1340	NO	UNK		C	UNK	1"
1.0.3	1059000		60 Middlefield Rd	60 Middlefield Rd-/8-1375	NO	UNK		C	UNK	1"
1.0.3	1059000		84 Middlefield Rd	84 Middlefield Rd-/8-1335	NO	UNK		C	UNK	1"
1.0.3	1059000		68 Middlefield Rd	68 Middlefield Rd-/8-1360	NO	UNK		C	UNK	1"
1.0.3	1059000		72 Middlefield Rd	72 Middlefield Rd-/8-1355	NO	UNK		C	UNK	1"
1.0.3	1059000		61 Middlefield Rd	61 Middlefield Rd-/8-1380	NO	UNK		C	UNK	1"
1.0.3	1059000		67 Middlefield Rd	67 Middlefield Rd-/8-1370	NO	UNK		C	UNK	
1.0.3	1059000		59 Middlefield Rd	59 Middlefield Rd-/8-1385	NO	UNK		C	UNK	1"
1.0.3	1059000		45 Middlefield Rd	45 Middlefield Rd-/8-1425	NO	UNK		C	UNK	1"
1.0.3	1059000		36 Middlefield Rd	36 Middlefield Rd-/8-1435	NO	UNK		C	UNK	
1.0.3	1059000		57 Middlefield Rd	57 Middlefield Rd-/8-1391	NO	UNK		C	UNK	1"
1.0.3	1059000		53 Middlefield Rd	53 Middlefield Rd-/8-1401	NO	UNK		C	UNK	1"
1.0.3	1059000		32 Middlefield Rd	32 Middlefield Rd-/8-1440	NO	UNK		C	UNK	1"
1.0.3	1059000		56 Middlefield Rd	56 Middlefield Rd-/8-1405	NO	UNK		C	UNK	1"
1.0.3	1059000		52 Middlefield Rd	52 Middlefield Rd-/8-1410	NO	UNK		C	UNK	
1.0.3	1059000		29 Middlefield Rd	29 Middlefield Rd-/8-1445	NO	UNK		C	UNK	1"

## Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
2003	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	MF
2004	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	C	3/8"	PLB	NON-LEAD	F	V	SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	C	3/8"	PLB	NON-LEAD	F	V	SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
2004	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2003	UNK-NOLG		PLB	NON-LEAD	V	A	MF
2004	C	5/8"	PLB	NON-LEAD	C	V	MF
2003	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2003	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2003	UNK-NOLG		PLB	NON-LEAD	F	A	MF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
2004	C	3/4"	2020	NON-LEAD	F	V	MF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF

Chester-1059000-Service\_Line\_In

poe_pou_treatment	building_plumbing_material_1	building_plumbing_material_2	building_plumbing_material_install_date	sampling_plan_location	tier	replaced_sl	replaced_material
NO	C						
NO	C	PEX					
	C						
	C						
NO	C						
NO	C						
NO							
NO	C						
	C						

replacement_date	comments
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003 Statistical Analysis on Private Side
	Basement inspection conducted 3/22/2024 and owner indicated the private side had been replaced at some point. Second basement inspection conducted 11/18/2024; Record drawing confirmed public side replaced in 2003 when the
	Statistical Analysis on Private Side
	Basement inspection conducted 3/22/2024
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Basement inspection completed on 8/3/24
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Basement Inspection completed on 8/3/24
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003; unable to determine service line material from self-reported photos - additional photos/tests required Statistical Analysis on
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Basement inspection completed on 1/23/24
	Basement inspection conducted 3/22/2024; Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003
	Basement inspection conducted 8/10/24; Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003
	Basement inspection conducted 3/22/2024; Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003
	Basement inspection conducted 7/27/24; Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003
	Basement inspection conducted 8/3/24
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003 Statistical Analysis on Private Side
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003 Statistical Analysis on Private Side
	Self-reported photos confirm private side material is copper
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003 Statistical Analysis on Private Side
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003 Statistical Analysis on Private Side
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Vacuum Excavation conducted 2024 Statistical
	Two-family with 56 and 58 Middlefield Rd. Basement inspection conducted 1/23/2024; Record drawing confirmed public side replaced in 2003 when the
	Basement inspection conducted 3/22/2024 and owner stated private side was
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Basement inspection conducted on 8/3/24

## Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		46 Middlefield Rd	46 Middlefield Rd-/8-1422	NO	UNK		C	UNK	1"
1.0.3	1059000		40 Middlefield Rd	40 Middlefield Rd-/8-1430	NO	UNK		C	UNK	
1.0.3	1059000		24 Middlefield Rd	24 Middlefield Rd-/8-1450	NO	UNK		C	UNK	1"
1.0.3	1059000		28 Middlefield Rd	28 Middlefield Rd-/8-1455	NO	UNK		C	UNK	1"
1.0.3	1059000		25 Middlefield Rd	25 Middlefield Rd-/8-1460	NO	UNK		C	UNK	1"
1.0.3	1059000		21 Middlefield Rd	21 Middlefield Rd-/8-1465	NO	UNK		C	UNK	1"
1.0.3	1059000		9 Middlefield Rd	9 Middlefield Rd-/8-1475	NO	UNK		C	UNK	
1.0.3	1059000		15 Middlefield Rd	15 Middlefield Rd-/8-1480	NO	UNK		C	UNK	
1.0.3	1059000		40 Hampden St	40 Hampden St-/8-1505	YES	UNK		C	UNK	
1.0.3	1059000		84 Hampden St	84 Hampden St-/8-1490	NO	UNK		C	UNK	
1.0.3	1059000		92 Hampden St	92 Hampden St-/8-1485	NO	UNK		C	UNK	
1.0.3	1059000		68 Hampden St	68 Hampden St-/8-1500	NO	UNK		C	UNK	
1.0.3	1059000		28 Hampden St	28 Hampden St-/8-1515	NO	UNK		C	UNK	
1.0.3	1059000		76 Hampden St	76 Hampden St-/8-1495	NO	UNK		C	UNK	
1.0.3	1059000		174 Route 20	174 Route 20-/8-1170	NO	UNK		C	UNK	1"
1.0.3	1059000		64 Middlefield Rd	64 Middlefield Rd-/8-1365	NO	UNK		C	UNK	1"
1.0.3	1059000		16 Hampden St	16 Hampden St-/8-1530	NO	UNK		C	UNK	
1.0.3	1059000		20 Hampden St	20 Hampden St-/8-1525	NO	UNK		C	UNK	
1.0.3	1059000		24 Hampden St	24 Hampden St-/8-1520	NO	UNK		C	UNK	
1.0.3	1059000		32 Hampden St	32 Hampden St-/8-1510	NO	UNK		C	UNK	
1.0.3	1059000		8 Hampden St	8 Hampden St-/8-1536	NO	UNK		C	UNK	
1.0.3	1059000		2 Town Rd	2 Town Rd-/8-1550	NO	UNK		C	UNK	
1.0.3	1059000		1 Town Rd	1 Town Rd-/8-1555	NO	UNK		C	UNK	
1.0.3	1059000		2 Hampden St	2 Hampden St-/8-1557	NO	UNK		C	UNK	
1.0.3	1059000		10 Hampden St	10 Hampden St-/8-1541	YES	UNK		C	UNK	
1.0.3	1059000		14 Middlefield Rd	14 Middlefield Rd-/8-1471	NO	UNK		C	UNK	1"
1.0.3	1059000		5 Main St	5 Main St-/8-1595	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		240 Route 20	240 Route 20-/8-1590	NO	UNK		C	UNK	1"
1.0.3	1059000		214 Route 20	214 Route 20-/8-1600	NO	UNK		C	UNK	1"
1.0.3	1059000		248 Route 20	248 Route 20-/8-1585	NO	UNK		C	UNK	1"

## Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
2003	C	3/4"	PLB	NON-LEAD	F	V	MF
2004	C	3/4"	PLB	NON-LEAD	F	V	SF
2004	C	1/2"	PLB	NON-LEAD	F		SF
2003	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	C	1/2"	PLB	NON-LEAD	F	V	SF
2003	C	3/4"	PLB	NON-LEAD	V		SF
2004	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2004	C	3/4"	PLB	NON-LEAD	F	V	NONRES
2007	C	3/4"	1978	NON-LEAD	F	V	SF
2007	C	1/2"	PLB	NON-LEAD	F	V	SF
2007	C	3/4"	PLB	NON-LEAD	F	V	SF
2007	C	3/4"	PLB	NON-LEAD	F	V	SF
2007	C	3/4"	PLB	NON-LEAD	F	V	SF
2007	C	3/4"	PLB	NON-LEAD	F	V	SF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	MF
2003	UNK-NOLG		PLB	NON-LEAD	V	A	MF
2007	C	3/4"	PLB	NON-LEAD	C	V	SF
2007	C	3/4"	PLB	NON-LEAD	F	V	SF
2007	C	3/4"	PLB	NON-LEAD	F	V	SF
2007	C	1/2"	PLB	NON-LEAD	F	V	SF
2007	C	3/4"	PLB	NON-LEAD	F	V	SF
PLB	C	3/4"	PLB	NON-LEAD	F	V	NONRES
PLB	C	3/4"	PLB	NON-LEAD	F	V	SF
PLB	C	3/4"	PLB	NON-LEAD	F	V	SF
2007	C	3/4"	PLB	NON-LEAD	F	V	SF
2003	C	2"	PLB	NON-LEAD	F	V	NONRES
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	MF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	MF
2011	C	3/4"	PLB	NON-LEAD	C	V	SF

Chester-1059000-Service\_Line\_In

poe_pou_treatment	building_plumbing_material_1	building_plumbing_material_2	building_plumbing_material_install_date	sampling_plan_location	tier	replaced_sl	replaced_material
	C						
NO	C						
YES	C						
NO	C		1981	A	TIER 4		
NO	C						
YES	C						
NO	C						
NO	C						
NO	C						
NO							
NO	C						
NO	C						
	C						
	C						
NO	C	PEX	1890	R	TIER 4		

replacement_date	comments
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Basement inspection conducted on 8/3/24
	7-21-25 PWS Private side inspection
	Basement inspection conducted 11/17/2024; Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Vacuum
	Basement inspection conducted 2/12/2024; Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Vacuum
	Basement inspection conducted 3/22/2024
	Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Vacuum
	Statistical Analysis on Private Side
	Town Hall; Basement inspection conducted 1/8/2024
	Basement Inspection conducted by PWS
	Basement inspection conducted 3/22/2024
	Basement Inspection conducted by PWS
	Basement inspection conducted 3/22/2024
	Basement inspection conducted 3/22/2024
	Basement inspection conducted 8/30/2024; self-reported photos confirm
	Two-family with 174 and 176 Route 20; Record drawing confirmed curb stop was replaced in 2010 when the main was replaced in August 2010. Statistical
	Two-family with 62 and 64 Middlefield Rd; Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Statistical
	Basement inspection attempted 3/22/2024, but owner self reported 3/4" copper and that interior plumbing is not lead but has lead solder
	Basement inspection conducted 3/22/2024
	Basement inspection conducted 5/1/2024 and owner stated private side was replaced in 2011
	Basement inspection conducted 3/22/2024 and owner stated private side was replaced in 2011
	Basement Inspection conducted by PWS
	DPW/Chester Town Garage; Basement inspection conducted 1/8/2024
	Basement inspection conducted 4/2/2024
	Basement inspection conducted 5/1/2024
	Basement inspection conducted 3/22/2024
	Chester Baptist Church (former school); Basement inspection conducted 1/8/2024; Record drawing confirmed public side replaced in 2003 when the main was replaced in October 2003. Vacuum
	Multiple buildings on property, but only one has a water service. Statistical Analysis on Public Side. Statistical Analysis on Private Side
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in July 2010. Statistical Analysis on Private Side
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011; self-reported photos confirm private side material is

## Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		241 Route 20	241 Route 20-/8-1560	NO	UNK		C	UNK	1"
1.0.3	1059000		253 Route 20	253 Route 20-/8-1570	NO	UNK		C	UNK	1"
1.0.3	1059000		254 Route 20	254 Route 20-/8-1580	NO	UNK		C	UNK	1"
1.0.3	1059000		259 Route 20	259 Route 20-/8-1577	NO	UNK		C	UNK	1"
1.0.3	1059000		4 Main St	4 Main St-/8-1636	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		6 Main St	6 Main St-/8-1640	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		245 Route 20	245 Route 20-/8-1565	NO	UNK		C	UNK	1"
1.0.3	1059000		222 Route 20	222 Route 20-/8-1615	NO	UNK		C	UNK	1"
1.0.3	1059000		218 Route 20	218 Route 20-/8-1605	NO	UNK		C	UNK	1"
1.0.3	1059000		217 Route 20	217 Route 20-/8-1625	NO	UNK		C	UNK	1"
1.0.3	1059000		17 River Front Rd	17 River Front Rd-/8-1666	NO	UNK		C	UNK	
1.0.3	1059000		19 River Front Rd	19 River Front Rd-/8-1661	NO	UNK		C	UNK	
1.0.3	1059000		5, 7, and 9 River Front Rd	5, 7, and 9 River Front Rd-/8-1685	YES	UNK		C	UNK	
1.0.3	1059000		15 River Front Rd	15 River Front Rd-/8-1670	NO	UNK		C	UNK	
1.0.3	1059000		11 River Front Rd	11 River Front Rd-/8-1675	NO	UNK		C	UNK	
1.0.3	1059000		12 Riverfront Rd	12 Riverfront Rd-/8-1680	NO	UNK		C	UNK	
1.0.3	1059000		12 Baker Ave	12 Baker Ave-/8-1650	NO	UNK		C	UNK	
1.0.3	1059000		14 Main St	14 Main St-/8-1655	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		10 Baker Ave	10 Baker Ave-/8-1646	NO	UNK		C	UNK	
1.0.3	1059000		26 Main St	26 Main St-/8-1710	NO	UNK		C	UNK	
1.0.3	1059000		15 Main St	15 Main St-/8-1700	NO	UNK		C	UNK	
1.0.3	1059000		20 Main St	20 Main St-/8-1690	NO	UNK		C	UNK	
1.0.3	1059000		31 Main St	31 Main St-/8-1725	NO	UNK		C	UNK	
1.0.3	1059000		11 Main St	11 Main St-/8-1695	NO	UNK		C	UNK	
1.0.3	1059000		24 Main St	24 Main St-/8-1705	NO	UNK		C	UNK	
1.0.3	1059000		27 Main St	27 Main St-/8-1735	NO	UNK		C	UNK	
1.0.3	1059000		30 Main St	30 Main St-/8-1715	NO	UNK		C	UNK	
1.0.3	1059000		29 Main St	29 Main St-/8-1730	NO	UNK		C	UNK	
1.0.3	1059000		14 Maple St	14 Maple St-/8-1755	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		10 Maple St	10 Maple St-/8-1745	YES	UNK		C	UNK	

## Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
2011	C	3/4"	PLB	NON-LEAD	F	V	NONRES
2011	C	3/4"	2018	NON-LEAD	F	V	SF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2011	C	1"	PLB	NON-LEAD	F	V	SF
1995	C	3/4"	PLB	NON-LEAD	F	V	NONRES
1995	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2011	C	3/4"	PLB	NON-LEAD	F	V	MF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2010	C	3/4"	PLB	NON-LEAD	C	V	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	C	3/4"	PLB	NON-LEAD	F	V	MF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1993	UNK-NOLG		PLB	NON-LEAD	V	A	SF
PLB	C	1"	PLB	NON-LEAD	F	V	SF
PLB	UNK-NOLG		1995	NON-LEAD	V	A	NONRES
PLB	C		PLB	NON-LEAD	V		SF
1992	C	3/4"	PLB	NON-LEAD	F	V	MIX
1992	UNK-NOLG		PLB	NON-LEAD	V	A	MIX
1992	C	3/4"	PLB	NON-LEAD	F	V	MIX
1992	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
1992	C	1"	PLB	NON-LEAD	F	V	SF
1992	UNK-NOLG		PLB	NON-LEAD	V	A	MIX
1992	UNK-NOLG		PLB	NON-LEAD	V	A	MIX
1992	UNK-NOLG		PLB	NON-LEAD	V	A	MIX
1992	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	C	3/4"	PLB	NON-LEAD	F	V	SF

Chester-1059000-Service\_Line\_In

poe_pou_treatment	building_plumbing_material_1	building_plumbing_material_2	building_plumbing_material_install_date	sampling_plan_location	tier	replaced_sl	replaced_material
NO	C						
NO	C						
NO	C						
NO	C		1900	R	TIER 5		
NO	C						
NO	O						
NO	C						
UNK	C		1900	R	TIER 4		

replacement_date	comments
	Carm's Restaurant and Coffee Shop. Basement inspection conducted 1/8/2024; Record drawing confirmed public side was replaced in 2011 when the main
	Basement inspection conducted on 8/3/24. Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Basement inspection conducted 5/1/2024; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Chester Theater Company. Basement inspection conducted 8/30/24. Main
	Main replaced around September 1995. Statistical Analysis on Private Side
	Basement inspection conducted 5/1/2024; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in July 2010. Statistical Analysis on Private Side
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in July 2010. Statistical Analysis on Private Side
	Record drawing confirmed public side was replaced in 2010 when the main was replaced in July 2010; self-reported photos confirm private side is copper
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	3-family numbers 5, 7, and 9; #7 Riverfront is sample location; Basement inspection conducted 5/1/2024
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Basement inspection conducted 5/1/2024. (Was listed as 12 Main St, but 12 Main St is not in customer billing list nor assessor's database, and is actually 12
	Lightfield Foundation office. Main replaced around September 1995; unable to determine private side service line material from self-reported photos -
	7-8-25 PWS private side inspection
	Statistical Analysis on Private Side
	Basement Inspection conducted by PWS
	Statistical Analysis on Private Side
	Stores Statistical Analysis on Private Side
	Basement inspection conducted 5/1/2024
	Statistical Analysis on Private Side
	Chester Common Table; Restaurant and Apartments Statistical Analysis on
	Classic Pizza Statistical Analysis on Private Side
	Records review confirmed public side services were replaced post-lead ban.
	Basement inspection conducted 5/1/2024

Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		6 Maple St	6 Maple St-/8-1740	NO	UNK		C	UNK	
1.0.3	1059000		12 Maple St	12 Maple St-/8-1750	NO	UNK		C	UNK	
1.0.3	1059000		7 Andrews Ave	7 Andrews Ave-/8-1765	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		5 Andrews Ave	5 Andrews Ave-/8-1761	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		16 Maple St	16 Maple St-/8-1770	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		33 Maple Ave	33 Maple Ave-/8-1795	NO	UNK		C	UNK	
1.0.3	1059000		31 Maple Ave	31 Maple Ave-/8-1800	NO	UNK		C	UNK	
1.0.3	1059000		29 Maple Ave	29 Maple Ave-/8-1805	NO	UNK		C	UNK	
1.0.3	1059000		30 Maple Ave	30 Maple Ave-/8-1780	NO	UNK		C	UNK	3/4"
1.0.3	1059000		35 Maple Ave	35 Maple Ave-/8-1790	NO	UNK		C	UNK	
1.0.3	1059000		27 Maple Ave	27 Maple Ave-/8-1810	NO	UNK		C	UNK	
1.0.3	1059000		26 Maple St	26 Maple St-/8-1815	NO	UNK		C	UNK	
1.0.3	1059000		32 Maple Ave	32 Maple Ave-/8-1775	NO	UNK		C	UNK	3/4"
1.0.3	1059000		21 Maple St	21 Maple St-/8-1820	NO	UNK		C	UNK	
1.0.3	1059000		23 Maple St	23 Maple St-/8-1830	NO	UNK		C	UNK	
1.0.3	1059000		9 Maple St	9 Maple St-/8-1850	NO	UNK		C	UNK	
1.0.3	1059000		19 Maple St	19 Maple St-/8-1835	NO	UNK		C	UNK	
1.0.3	1059000		7 Maple St	7 Maple St-/8-1856	NO	UNK		C	UNK	
1.0.3	1059000		11 Maple St	11 Maple St-/8-1845	NO	UNK		C	UNK	
1.0.3	1059000		5 Maple St	5 Maple St-/8-1860	NO	UNK		C	UNK	
1.0.3	1059000		17 Maple St	17 Maple St-/8-1840	NO	UNK		C	UNK	
1.0.3	1059000		10 Prospect St	10 Prospect St-/8-1870	NO	UNK		C	UNK	
1.0.3	1059000		44 Prospect St	44 Prospect St-/8-1880	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		77 Prospect St	77 Prospect St-/8-1895	NO	UNK		C	UNK	
1.0.3	1059000		61 Prospect St	61 Prospect St-/8-1885	NO	UNK		C	UNK	
1.0.3	1059000		71 Prospect St	71 Prospect St-/8-1890	NO	UNK		C	UNK	
1.0.3	1059000		17 Main St	17 Main St-/8-1865	YES	UNK		C	UNK	
1.0.3	1059000		108 Prospect St	108 Prospect St-/8-1905	NO	UNK		C	UNK	3/4"
1.0.3	1059000		100 Prospect St	100 Prospect St-/8-1897B	YES	UNK		C	UNK	
1.0.3	1059000		105 Prospect St	105 Prospect St-/8-1911	NO	UNK		C	UNK	
1.0.3	1059000		117 Prospect St	117 Prospect St-/8-1915	NO	UNK		C	UNK	
1.0.3	1059000		124 Prospect St	124 Prospect St-/8-1930	NO	UNK		C	UNK	
1.0.3	1059000		120 Prospect St	120 Prospect St-/8-1920	NO	UNK		C	UNK	
1.0.3	1059000		25 Maple St	25 Maple St-/8-1825	NO	UNK		C	UNK	
1.0.3	1059000		114 Prospect St	114 Prospect St-/8-1925	NO	UNK		C	UNK	
1.0.3	1059000		121 Prospect St	121 Prospect St-/8-1936	NO	UNK		C	UNK	

Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
1992	UNK-NOLG		PLB	NON-LEAD	V	A	MF
1992	B	3/4"	PLB	NON-LEAD	F	V	SF
1992	UNK-NOLG	3/4"	PLB	NON-LEAD	F	V	SF
1992	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	C	3/8"	PLB	NON-LEAD	F	V	MF
1992	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	UNK-NOLG		PLB	NON-LEAD	F	A	SF
1992	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	C	3/4"	PLB	NON-LEAD	F	V	SF
1992	C	3/4"	PLB	NON-LEAD	F	V	SF
1992	C	3/4"	PLB	NON-LEAD	F		SF
1992	C	3/4"	PLB	NON-LEAD	F	V	SF
1992	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	C	3/4"	PLB	NON-LEAD	F	V	SF
1992	C	3/4"	PLB	NON-LEAD	F	V	SF
1992	C	3/4"	PLB	NON-LEAD	F	V	SF
ALB	C		PLB	NON-LEAD	F		NONRES
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2022	C		2022	NON-LEAD	F		SF
ALB	C	3/4"	2002	NON-LEAD	C	V	SF
2022	C		2022	NON-LEAD	F		SF
1992	C	1 1/2"	ALB	NON-LEAD	F	V	MIX
1991	UNK-NOLG		PLB	NON-LEAD	F	A	SF
ALB	C	3/4"	PLB	NON-LEAD	F	V	SF
1991	PVC	3/4"	PLB	NON-LEAD	F	V	SF
1991	C	3/4"	PLB	NON-LEAD	F	V	SF
1991	UNK-NOLG		PLB	NON-LEAD	V	A	MF
1991	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1992	C	3/4"	PLB	NON-LEAD	F	V	SF
1991	UNK-NOLG		PLB	NON-LEAD	V	A	MF
1991	UNK-NOLG	3/4"	PLB	NON-LEAD	V	A	SF



replacement_date	comments
	Statistical Analysis on Private Side
	Basement inspection conducted 8/19/25 showed service was brass
	Basement inspection conducted 1/8/2024 indicated cast iron, but unknown if lined or unlined. Records review confirmed public side services were replaced
	Records review confirmed public side services were replaced post-lead ban.
	Basement Inspection Conducted 9/4/24. Records review confirmed public side
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Vacuum Excavation conducted 2024 Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Basement inspection conducted 5/1/2024 and noted point of entry treatment
	Basement inspection conducted 4/29/2024 and noted point of use treatment
	Basement inspection conducted 4/29/2024 and noted point of entry treatment system present. Second basement inspection conducted 9/16/2024 and found no treatment and copper and plastic interior plumbing. Vacuum Excavation
	Basement inspection conducted 12/21/2023
	Statistical Analysis on Private Side
	Basement inspection conducted 9/13/2024; self-reported photos confirm
	Basement inspection conducted 12/20/2023
	Statistical Analysis on Private Side
	Basement inspection conducted 9/13/2024 and noted PVC on interior plumbing
	Public side Inspection by Town on 8/21/25
	Former two-family that used to be 15 and 17 Maple St, but renovated into a single family with 17 Maple as address. Basement inspection conducted
	Public side and Private side physically inspected during a line repair in 2021
	Statistical Analysis on Public Side Statistical Analysis on Private Side
	Service replaced by water department in 2022
	Self-reported photos confirm private side material is copper
	Service replaced by Water Department in 2022
	Basement inspection conducted 1/11/2024
	Vacuum Excavation conducted 2024 Statistical Analysis on Private Side
	Basement inspection conducted 2/12/2024
	Basement inspection conducted 11/18/2024 and noted black PVC on private
	Basement inspection conducted 3/6/2024
	Two-family Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Rental Property; Basement inspection conducted 12/21/2023
	Two-family Statistical Analysis on Private Side
	Unable to determine private side service line materials from self-reported photos - additional tests/photos required Statistical Analysis on Private Side

Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		129 Prospect St	129 Prospect St-/8-1940	NO	UNK		C	UNK	
1.0.3	1059000		134 Prospect St	134 Prospect St-/8-1950	NO	UNK		C	UNK	
1.0.3	1059000		149 Prospect St	149 Prospect St-/8-1955	NO	UNK		C	UNK	
1.0.3	1059000		128 Prospect St	128 Prospect St-/8-1945	YES	UNK		C	UNK	
1.0.3	1059000		155 Prospect St	155 Prospect St-/8-1960	NO	UNK		C	UNK	
1.0.3	1059000		158 Prospect St	158 Prospect St-/8-1970	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		138 Prospect St	138 Prospect St-/8-1966	NO	UNK		C	UNK	
1.0.3	1059000		171 Prospect St	171 Prospect St-/8-1980	NO	UNK		C	UNK	
1.0.3	1059000		164 Prospect St	164 Prospect St-/8-1991	NO	UNK		C	UNK	
1.0.3	1059000		166 Prospect St	166 Prospect St-/8-1985	NO	UNK		C	UNK	
1.0.3	1059000		14 Soisalo Rd	14 Soisalo Rd-/8-1975	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		160 Prospect St	160 Prospect St-/8-1995	NO	UNK		C	UNK	
1.0.3	1059000		11 Prospect St	11 Prospect St-/8-2000	NO	UNK		C	UNK	
1.0.3	1059000		9 Prospect St	9 Prospect St-/8-2005	NO	UNK		C	UNK	
1.0.3	1059000		6 Emery St	6 Emery St-/8-2015	NO	UNK		C	UNK	1"
1.0.3	1059000		101 Emery St	101 Emery St-/8-2035	NO	UNK		C	UNK	
1.0.3	1059000		2 Emery St	2 Emery St-/8-2010	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		12 Emery St	12 Emery St-/8-2025	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		102 Emery St	102 Emery St-/8-2040	NO	UNK		C	UNK	
1.0.3	1059000		277 Route 20	277 Route 20-/8-2050	NO	UNK		C	UNK	1"
1.0.3	1059000		289 Route 20	289 Route 20-/8-2062	NO	UNK		C	UNK	1"
1.0.3	1059000		295 Route 20	295 Route 20-/8-2070	NO	UNK		C	UNK	1"
1.0.3	1059000		291 Route 20	291 Route 20-/8-2065	NO	UNK		C	UNK	1"
1.0.3	1059000		263 Route 20/263 Huntington Rd	263 Route 20/263 Huntington Rd-/8-2045	YES	UNK		C	UNK	1"
1.0.3	1059000		279 Route 20	279 Route 20-/8-2055	NO	UNK		C	UNK	1"
1.0.3	1059000		313 Route 20	313 Route 20-/8-2085	NO	UNK		C	UNK	1"
1.0.3	1059000		303 Route 20	303 Route 20-/8-2076	NO	UNK		C	UNK	1"
1.0.3	1059000		317 Route 20	317 Route 20-/8-2090	NO	UNK		C	UNK	1"
1.0.3	1059000		50 Bay State Dr	50 Bay State Dr-/8-2111	NO	UNK		UNK-NOLG	UNK	

## Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
1991	C	3/4"	PLB	NON-LEAD	C	V	SF
1991	C	3/4"	PLB	NON-LEAD	C	V	SF
1991	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1991	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1991	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1991	C	3/4"	PLB	NON-LEAD	F	V	SF
1991	C	3/4"	PLB	NON-LEAD	F		SF
1991	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1991	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2024	UNK-NOLG		PLB	NON-LEAD	F		SF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
1991	C	1"	PLB	NON-LEAD	C	V	SF
ALB	C		PLB	NON-LEAD	C	V	SF
ALB	C		PLB	NON-LEAD	C	V	SF
PLB	C	3/4"	PLB	NON-LEAD	F		SF
PLB	C	3/4"	PLB	NON-LEAD	F		SF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
PLB	C	3/4"	PLB	NON-LEAD	F		SF
2011	C	3/4"	PLB	NON-LEAD	F	V	SF
2011	C	1"	PLB	NON-LEAD	F	V	SF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2011	C	3/4"	PLB	NON-LEAD	F	V	SF
2011	C	1"	PLB	NON-LEAD	F	V	SF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	MF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
2011	B	3/4"	PLB	NON-LEAD	F	V	SF
2011	C	1"	PLB	NON-LEAD	F	V	SF
PLB	C	3/4"	PLB	NON-LEAD	F	A	NONRES

Chester-1059000-Service\_Line\_In

poe_pou_treatment	building_plumbing_material_1	building_plumbing_material_2	building_plumbing_material_install_date	sampling_plan_location	tier	replaced_sl	replaced_material
UNK	UNK		1900	R	TIER 4		
YES	C						
NO							
NO	C		1920	R	TIER 4		
	C						

replacement_date	comments
	Self-reported photos confirm private side material is copper
	Self-reported photos confirm private side material is copper
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Basement inspection conducted 11/6/2023
	PWS public and private side inspection 6-18-25
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Public side and Private side physically inspected during a line repair in 2024
	Statistical Analysis on Public Side Statistical Analysis on Private Side
	Self-reported photos confirm private side material is copper
	Basement inspection conducted 11/6/2024. Repairs made to service May 2025
	Basement Inspection Conducted on 8/30/24; Self-Reported photos confirm service line material. Water department fixed service line copper in 2021
	Self-reported photos do not show portion of service line entering the house Statistical Analysis on Public Side Statistical Analysis on Private Side
	Statistical Analysis on Public Side Statistical Analysis on Private Side
	Basement inspection conducted 4/29/2024 and noted point of use treatment system present. Public side physically inspected during service repair in 2021
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Basement Inspection 7-8-25
	Basement inspection conducted 5/1/2024; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Basement inspection conducted 8/30/24; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Basement inspection conducted 5/1/2024; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Two-family; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Verizon; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Basement inspection conducted 8/19/25 showed service was brass. T&B revised to non-lead. Record drawing confirmed public side was replaced in
	Basement inspection conducted 8/30/24; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Commercial warehouse. Basement inspection conducted 8/30/24. Statistical

## Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		309 Route 20	309 Route 20-/8-2080	NO	UNK		C	UNK	1"
1.0.3	1059000		323 Route 20	323 Route 20-/8-2100	NO	UNK		C	UNK	1"
1.0.3	1059000		319 Route 20	319 Route 20-/8-2095	NO	UNK		C	UNK	1"
1.0.3	1059000		312 Route 20	312 Route 20-/8-2110	NO	UNK		C	UNK	1"
1.0.3	1059000		300 Route 20	300 Route 20-/8-2120	NO	UNK		C	UNK	1"
1.0.3	1059000		292 Route 20	292 Route 20-/8-2125	NO	UNK		C	UNK	1"
1.0.3	1059000		284 Route 20	284 Route 20-/8-2135	NO	UNK		C	UNK	1"
1.0.3	1059000		306 Route 20	306 Route 20-/8-2115	NO	UNK		C	UNK	1"
1.0.3	1059000		288 Route 20	288 Route 20-/8-2130	NO	UNK		C	UNK	1"
1.0.3	1059000		278 Route 20	278 Route 20-/8-2140	NO	UNK		C	UNK	1"
1.0.3	1059000		272 Route 20	272 Route 20-/8-2145	NO	UNK		C	UNK	1"
1.0.3	1059000		268 Route 20	268 Route 20-/8-2155	NO	UNK		C	UNK	1"
1.0.3	1059000		91 Bay State Dr	91 Bay State Dr-/8-2180	NO	UNK		C	UNK	
1.0.3	1059000		90 Bay State Dr	90 Bay State Dr-/8-2185	NO	UNK		C	UNK	
1.0.3	1059000		260 Route 20	260 Route 20-/8-2165	NO	UNK		C	UNK	1"
1.0.3	1059000		264 Route 20	264 Route 20-/8-2160	NO	UNK		C	UNK	1"
1.0.3	1059000		381 Route 20	381 Route 20-/8-2190	NO	UNK		C	UNK	
1.0.3	1059000		404 Route 20	404 Route 20-/8-2210	NO	UNK		C	UNK	
1.0.3	1059000		400 Route 20	400 Route 20-/8-2206	NO	UNK		C	UNK	
1.0.3	1059000		396 Route 20	396 Route 20-/8-2201	NO	UNK		C	UNK	
1.0.3	1059000		412 Route 20/412 Huntington Rd	412 Route 20/412 Huntington Rd-/8-2215	YES	UNK		C	UNK	
1.0.3	1059000		405 Route 20	405 Route 20-/8-2221	NO	UNK		C	UNK	
1.0.3	1059000		428 Route 20	428 Route 20-/8-2240	NO	UNK		C	UNK	
1.0.3	1059000		421 Route 20	421 Route 20-/8-2225	NO	UNK		C	UNK	
1.0.3	1059000		430 Route 20	430 Route 20-/8-2245	NO	UNK		C	UNK	
1.0.3	1059000		416 Route 20	416 Route 20-/8-2230	NO	UNK		C	UNK	

## Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
2011	UNK-NOLG	3/4"	PLB	NON-LEAD	F	V	NONRES
2011	C	3/4"	PLB	NON-LEAD	F	V	SF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2011	C	3/4"	PLB	NON-LEAD	F	V	SF
2011	C	3/4"	PLB	NON-LEAD	F	V	NONRES
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	MIX
2011	C	3/4"	PLB	NON-LEAD	F	V	SF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2011	C	3/4"	PLB	NON-LEAD	F	V	MF
2011	C		1800s	NON-LEAD	F	V	SF
ALB	C	3/4"	PLB	NON-LEAD	F	V	SF
ALB	C		PLB	NON-LEAD	F		SF
2011	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
ALB	C	3/4"	PLB	NON-LEAD	F	V	NONRES
ALB	C	3/4"	PLB	NON-LEAD	F	V	SF
ALB	C	3/4"	PLB	NON-LEAD	F	V	SF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
ALB	C	3/4"	ALB	NON-LEAD	F	V	SF
ALB	C	3/4"	PLB	NON-LEAD	F	V	SF
ALB	UNK-NOLG		ALB	NON-LEAD	V		SF
ALB	C	3/4"	PLB	NON-LEAD	F	V	SF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	SF

Chester-1059000-Service\_Line\_In

poe_pou_treatment	building_plumbing_material_1	building_plumbing_material_2	building_plumbing_material_install_date	sampling_plan_location	tier	replaced_sl	replaced_material
NO	C						
NO	C						
NO	C						
NO	C		1990	R	TIER 5		
	C						

replacement_date	comments
	Post office; Basement inspection conducted 1/8/2024 indicated cast iron, but unknown if lined or unlined; Record drawing confirmed public side was
	Basement inspection conducted 5/1/2024; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Basement inspection conducted 5/1/2024 and owner stated private side was replaced in 1972-1973; Record drawing confirmed public side was replaced in
	Firehouse; Basement inspection conducted 1/8/2024; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Basement inspection conducted 8/10/24; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Two-family. Basement Inspection Conducted 8/30/24; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July
	Basement inspection conducted 8/30/24; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011.
	Basement Inspection 7-24-25 PWS
	PWS Public and private side inspection 7-18-25
	Quality Auto Sales and Service; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Wheeler Oil. Basement inspection conducted 1/8/2024
	Basement inspection conducted 3/22/2024
	Basement inspection conducted 1/8/2024
	Statistical Analysis on Private Side
	Basement inspection conducted 5/1/2024 and owner stated private side was installed in the 1990s
	Basement inspection conducted 1/8/2024
	Basement inspection conducted 3/14/2024
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side

Chester-1059000-Service\_Line\_In

version	pws_id	mf	site_id	locational_identifier	lcr_location	connector_present	conn	current_public_sl_material	public_sl_prev_lead	public_sl_size
1.0.3	1059000		433 Route 20	433 Route 20-/8-2251	NO	UNK		C	UNK	
1.0.3	1059000		424 Route 20	424 Route 20-/8-2236	NO	UNK		C	UNK	
1.0.3	1059000		437 Route 20	437 Route 20-/8-2255	NO	UNK		C	UNK	
1.0.3	1059000		436 Route 20	436 Route 20-/8-2260	NO	UNK		C	UNK	
1.0.3	1059000		454 Route 20	454 Route 20-/8-2265	NO	UNK		C	UNK	
1.0.3	1059000		463 Route 20	463 Route 20-/8-2272	NO	UNK		C	UNK	
1.0.3	1059000		475 Route 20	475 Route 20-/8-2276	NO	UNK		C	UNK	
1.0.3	1059000		476 Route 20	476 Route 20-/8-2281	NO	UNK		C	UNK	
1.0.3	1059000		221 Route 20	221 Route 20-/8-3330	NO	UNK		C	UNK	1"
1.0.3	1059000		270 Route 20/270 Huntington Rd	270 Route 20/270 Huntington Rd-/8-2151	NO	UNK		C	UNK	1"
1.0.3	1059000		78 Bay State Dr	78 Bay State Dr-/8-2175	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		1 School St	1 School St-/8-1195	NO	UNK		C	UNK	
1.0.3	1059000		28 Maple St	28 Maple St-/8-1785	NO	UNK		C	UNK	
1.0.3	1059000		122 Middlefield Rd	122 Middlefield Rd-/8-	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		2 Middlefield Rd	2 Middlefield Rd-/8-1630	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		327 Route 20	327 Route 20-/8-2105	NO	UNK		C	UNK	1"
1.0.3	1059000		12 Bay State Dr	12 Bay State Dr-/8-0061	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		18 Bay State Dr	18 Bay State Dr-/8-3460	NO	UNK		UNK-NOLG	UNK	
1.0.3	1059000		8 Emery St	8 Emery St-/TB-001	YES	UNK		UNK-NOLG	UNK	
1.0.3	1059000		104 Middlefield Rd	104 Middlefield Rd-/8- 1295	NO	UNK		C	UNK	
1.0.3	1059000		31 PROSPECT ST	31 PROSPECT ST-/8-1875	NO	UNK		C	UNK	3/4"
1.0.3	1059000		220 Route 20	220 Route 20-/8-1610	NO	UNK		C	UNK	1"
1.0.3	1059000		397 Route 20	397 Route 20-/TB-002	NO	UNK		C	UNK	
1.0.3	1059000		0 Route 20	0 Route 20-/No acct #	NO	UNK		C	UNK	1"
1.0.3	1059000		1 School St	1 School St-/8-1195-Fire	NO	UNK		C	UNK	
1.0.3	1059000		91 Prospect St	91 Prospect St-/8-1897A	YES	UNK		C	UNK	
1.0.3	1059000		86 Kabachunik Rd	86 Kabachunik Rd-/TB-266	NO	UNK		UNK-NOLG	UNK	

Chester-1059000-Service\_Line\_In

public_sl_install_date	current_private_sl_material	private_sl_size	private_sl_install_date	entire_service_line_classification	verification_method	other_verification_method	building_type
ALB	C	3/4"	PLB	NON-LEAD	F		SF
ALB	UNK-NOLG		ALB	NON-LEAD	V		SF
ALB	C	3/4"	PLB	NON-LEAD	F		SF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	MF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
ALB	C	1"	2014	NON-LEAD	F	V	SF
2010	C	1"	PLB	NON-LEAD	F	V	NONRES
2011	UNK-NOLG		PLB	NON-LEAD	V	A	SF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
1993	C	1"	PLB	NON-LEAD	F		MF
1992	UNK-NOLG	1"	PLB	NON-LEAD	F	V	SF
PLB	C	3/8"	PLB	NON-LEAD	F	A	MF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
2011	UNK-NOLG		PLB	NON-LEAD	V	A	MF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	SF
2004	UNK-NOLG		PLB	NON-LEAD	V	A	SF
PLB	UNK-NOLG		PLB	NON-LEAD	F	A	SF
2010	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
ALB	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
2011	UNK-NOLG		PLB	NON-LEAD	V	A	NONRES
2024	C		2024	NON-LEAD	F		MF
ALB	C	3/4"	PLB	NON-LEAD	F	V	SF
PLB	UNK-NOLG		PLB	NON-LEAD	V	A	SF

Chester-1059000-Service\_Line\_In

poe_pou_treatment	building_plumbing_material_1	building_plumbing_material_2	building_plumbing_material_install_date	sampling_plan_location	tier	replaced_sl	replaced_material
	C						
NO	C						
NO	C						
NO	C						
NO	C						
UNK	UNK		1900	A	TIER 5		
UNK	UNK		1880	R	TIER 4		

replacement_date	comments
	Basement inspection conducted 1/8/2024. Service line replaced by water
	Basement inspection conducted 3/15/2024. Service line repaired by Water
	Two-family Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Statistical Analysis on Private Side
	Basement inspection conducted 5/1/2024 and owner stated private side was replaced in 2014; self-reported photos confirm private side is copper
	Masonic Temple; Function Hall. Basement inspection conducted 5/1/2024, indicated no treatment and copper interior plumbing; Record drawing
	Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011; unable to determine private side material from self reported photos - additional photos/tests required Statistical Analysis on
	(Water Dept gave us address of 88 Bay State Dr, but it should be 78 as that is the address the assessor has. There is no 88) Statistical Analysis on Public
	Chester Commons Apartments and Library (Former Chester High School); Basement inspection conducted on 11/18/2024. Vacuum Excavation conducted
	Basement inspection conducted 5/1/2024 and noted a black pipe that was
	Basement inspection conducted 3/22/2024 Statistical Analysis on Public Side
	Cornerstone Christian Church Statistical Analysis on Public Side Statistical
	Two-family; Record drawing confirmed public side was replaced in 2011 when the main was replaced in July 2011. Statistical Analysis on Private Side
	Industrial, Manufactured Gas Storage Statistical Analysis on Public Side
	Revive Chester LLC, Manufacturing Facility Statistical Analysis on Public Side
	Inactive. House was demolished and new building was not connected to the water system; but service line could still be present (need to create a locational
	Inactive. Water meter has been removed, customer installed a well. Service line still present Statistical Analysis on Private Side
	Inactive. No active service/billing since prior to 1998. Vacuum Excavation conducted 2024. Statistical Analysis on Private Side.
	Chester Historical Sociatey (former jail house). Inactive. No active service/billing since prior to 2014; Record drawing confirmed public side was
	Inactive. Currently vacant developable land. Former Gem of the Valley. There is no account number. Service line could still be in the ground. (need to create a
	Chester Cemetery (located between 263 and 277 Route 20); Record drawing confirmed public side was replaced in 2011 when the main was replaced in July
	Fire service - entire service line inspected when installed in 2024 to Chester
	Basement inspection conducted 2/12/2024
	Statistical Analysis on Public Side Statistical Analysis on Private Side